Wire Installation Status



Ryan A. Grosso (on behalf of assembly team)

Collaboration
Meeting
May 10th, 2013

Preparing The Tent & TPC



- Tent Cleaned
- TPC Cleaned with Alcohol

* Special Thanks Bern Group

Power Washing Floor Grates



TPC Floor

- Plastic over field cage tubes
- Lay down floor grating
- Secure flooring with Zip Ties



Install Spacer Boards



Vertical Spacer Boards



Vertical Spacer Boards




Leakage Check

Leakage Current Test Stand







- Test each channel individually
- Place a bias of 400 V across each capacitor channel
- Look for current leakage across capacitors to be less than 0.2 microAmps



Y Plane



Delivered into TPC

Trade off boards






Install top horizontal

Install bottom horizontal





U & V Planes




Similar installation procedure

V plane U plane

Cover Plates

Continuity and Installation Check



- Check for electrical contact between wires and boards
- Look for deviations between wires
- Make sure no wires are out of place

Corner Boards




- Continuously wrapped
- SS wires not gold flashed





Tension & Alignment



Fine Adjustment



Tension Measurement




- Currently in process!
- Working with FNAL Alignment
- Might take some time(~1-2 weeks)

Alignment Yesterday

Parallel w.r.t to cathode

Corners: 90°± 0 .1°



- Worked with FNAL Alignment
- Fixed the positions of the vertical tension bars
- Shooting for 0.5mm tolerance in position of x, y, z
- Next steps
 - Align the top horizontal bar
 - Tension the wires

Thanks Wire Team!



Jen, Jonathan, Christoph,

Thomas, Roberto, Andrzej, Antonio, David, Sowjanya, Jason, Bryce, Sarah, Sam, Bonnie

